




100MM WIDE SPRING

M30 pivot assembly

SL, AL, SBL TIGHTENING TORQUES

M30 pivot assembly



IN ALL CASES TORQUE TIGHTEN INITIALLY
AFTER FIRST 2 WEEKS OF OPERATION OR
AFTER FIRST RUN UNDER LOAD CONDITIONS
AND THEN ANNUALLY.

① UNDER EXTREME CONDITIONS, WITH MORE FREQUENCY.